2400 BPS Internal Modem (250-3525) Results Codes Faxback Doc. # 4940

NUMBER	WORD	DESCRIPTION
0	OK	The modem successfully processed the command line.
1	CONNECT	The modem detected a carrier at 300 baud.
2	RING	The phone is ringing.
3	NO CARRIER	Carrier not detected within time limit or carrier lost.
4	ERROR	The modem could not process the command line (entry error).
5	CONNECT 1200	The modem detected a carrier at 1200 baud.
6	NO DIAL TONE	The modem couldn't detect a dial tone when dialing.
7	BUSY	Modem detected a busy signal.
8	NO ANSWER	Modem never detected silence (@ command only). continues to ring.
9	Not Used	
10	CONNECT 2400	The modem detected a carrier at 2400 baud.

(css 07/28/93)