1200 BPS Internal Modem (250-1013E) Result Codes Faxback Doc. # 4758

Numeric Code	Word Code	Result
0	OK	Command executed without error.
1	CONNECT	Carrier detected (300 bps or 1200 bps if X0 is set).
2	RING	Phone is ringing. Modem does not answer unless commanded to or unless auto-answer is enabled.
3	NO CARRIER	Carrier lost or never detected.
4	ERROR	Error in command line, line too long, or invalid character format.
5	CONNECT 1200	Carrier detected at 1200 bps if X1 is set.
6	NO DIAL TONE	No dial tone is detected within 5 seconds and X2 or X4 is set.
7	BUSY	Busy signal is detected and X3 or X4 is set.

Notes:

- * VO and V1 determine whether the modem returns numeric (VO) or verbal (V1) result codes.
- * Q determines whether or not results are sent.
- * The defaults for the V and Q commands are set by DIP switches on the modem board.
- * The X command also relates to the result code. Depending on the selected value of this command, the result code that appears varies.

(dkh-07/28/93)